



04/11/2025

TECHNICAL INFORMATION

Subject : Bisphenol A Absence.

RENOLIT Hispania, S.A, certifies that the articles manufactured.

ARTICLES

- B16595A1400.0115A CRISTAL 050 0180 21366 09992

do not contain Bisphenol A (CAS number: 80-05-7) in its composition.

Bisphenol A does not appear on composition of raw materials we use to produce RENOLIT articles, according to information included in raw materials Safety Data Sheet.

We cannot take any responsibility of unavoidable (min. concentrations) contaminations caused by technical processes regarding raw materials used.

Quality Department  Fdo. Natalia Oteiza	
--	---

RENOLIT Hispania S.A.

Poligono San Miguel
Avda. De los Castaños s/n
31132 Villatuerta (Navarra)
Spain

phone: +34 948.556315
fax: +34 948.554155
renolit.hispania@renolit.com
www.renolit.com